

**Left Photo (Top):** The damaged area of Piv's Restaurant had to be supported by steel beams in order for the restoration work to begin.

**Right Photo:** ACCORD Restoration temporarily secured the entire roof and closed up the wall to the damaged area allowing Piv's Restaurant to stay in business with minimal loss of income.

# **Project Spotlight: Piv's Restaurant - Car Crash**

#### Cause

A car crashed through the front of Piv's Restaurant in Cockeysville, Maryland.

## **Damage Description**

ACCORD Restoration responded as soon as the call was received to assess the damage. The front wall of Piv's Restaurant was damaged along with a major steel support beam and had to be replaced.

### **Action**

The accident happened during football season, which is a prime revenue time for the restaurant. Keeping this in mind, ACCORD Restoration closed off the damaged wall, allowing Piv's to stay in business throughout the restoration project with minimal loss of income. ACCORD Restoration also temporarily secured the entire roof and replaced a damaged structural steel "I" beam that ran the entire length of the restaurant. Throughout the project, ACCORD Restoration coordinated all aspects of the job, including laborers, sub-contractors and insurance adjusters.

# Impact on Claim

ACCORD Restoration repaired all damages and restored the restaurant back to its pre-loss condition. The restoration process took three months to complete.

